

Characterizing the degradation of Army primers by the AC-DC-AC accelerated test method

Vinod Upadhyay, Kerry N. Allahar, Gordon P. Bierwagen

Department of Coatings and Polymeric Materials North Dakota State University, Fargo ND 58105

Army Corrosion Summit 2010, Huntsville, Alabama

This work was supported by the Army Research Laboratory, Contract No. W911NF-04-2-0029.

including suggestions for reducing	completing and reviewing the collect this burden, to Washington Headqu uld be aware that notwithstanding ar DMB control number.	arters Services, Directorate for Infor	mation Operations and Reports	, 1215 Jefferson Davis	Highway, Suite 1204, Arlington	
1. REPORT DATE FEB 2010	2. REPORT TYPE			3. DATES COVERED 00-00-2010 to 00-00-2010		
4. TITLE AND SUBTITLE				5a. CONTRACT NUMBER		
Characterizing the degradation of Army primers by the AC-DC-AC accelerated test method				5b. GRANT NUMBER		
accelerated test method				5c. PROGRAM ELEMENT NUMBER		
6. AUTHOR(S)				5d. PROJECT NUMBER		
				5e. TASK NUMBER		
				5f. WORK UNIT NUMBER		
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) North Dakota State University, Department of Coatings and Polymeric Materials, Fargo, ND, 58105				8. PERFORMING ORGANIZATION REPORT NUMBER		
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)				10. SPONSOR/MONITOR'S ACRONYM(S)		
				11. SPONSOR/MONITOR'S REPORT NUMBER(S)		
12. DISTRIBUTION/AVAIL Approved for publ	LABILITY STATEMENT ic release; distributi	ion unlimited				
13. SUPPLEMENTARY NO 2010 U.S. Army Co	otes orrosion Summit, H	untsville, AL, 9-11 I	Feb. U.S. Governi	nent or Fede	ral Rights License	
14. ABSTRACT						
15. SUBJECT TERMS						
16. SECURITY CLASSIFIC	17. LIMITATION OF ABSTRACT	18. NUMBER OF PAGES	19a. NAME OF RESPONSIBLE PERSON			
a. REPORT unclassified	b. ABSTRACT unclassified	c. THIS PAGE unclassified	Same as Report (SAR)	16	RESPONSIBLE PERSON	

Public reporting burden for the collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and

Report Documentation Page

Form Approved OMB No. 0704-0188


Accelerated Testing Methods


Salt spray
ASTM B-117






Prohesion exposure ASTM G85-14






- Simulate weathering conditions
- Periodic testing at given number of cycles
 - Visual inspection for failure, Electrochemical methods (EIS, ENM)
- Exposure times in excess of weeks or months for failure

AC-DC-AC accelerated testing method




Cycles

- AC-step (EIS/ENM, measurement step)
- Cathodic potential dc-step(stressing step)
- Rest/equilibration/relaxation process



Fe
$$\longrightarrow$$
 Fe²⁺ + 2e⁻
 $O_2 + 2H_2O + 4e^- \longrightarrow 4OH^-$
 $2H_2O + 2e^- \longrightarrow 2OH^- + H_2$
*Corrosion reactions, ions/electrolyte exit from primer, pore formation


Consequences of the DC condition



- ➤ Passage of ions can cause coating deterioration and formation of transport pathways in coatings
- >Film delamination at interface if cathodic reactions take place


Army Corrosion Summit 2007

- Steel substrate
- Polyurethane CARC
 - (MIL-DTL-64159 Type 2)
- Epoxy Primer
 - (MIL-P-53022B Type II,)
- 3.5 wt % NaCl electrolyte
- -2 V and -4 V cycles had no influence
- After 12 -8 V cycles, coating system failed




Immersion time / days or cycle number

Army Summit 2008



- Steel substrate, Epoxy Primer (MIL-P-53022B Type II,)
- 3.5 wt % NaCl electrolyte
- No observable influence on D_{H2O} and water uptake

Experimental setup




- Substrate Steel R-36 supplied by Q-panels
- Coatings- 2 epoxy primers with specification of MIL-P-53022b Type II (D and S)
- Testing method: AC-DC-AC via Electrochemical Impedance Spectroscopy.
- Electrolyte: 5.0 % NaCl
- Sample was immersed in 5.0 % NaCl solution during EIS.

Gamry instrumentation and software

- >EIS-: 100 kHz to 10 mHz, 10 mV amplitude, 10 points per decade
- >Test cell-: clamp-on persplex cylinder with O-ring seal (7.07 cm²)
- >Modeling done using Zsimpwin provided by Princeton applies research


Influence of DC on current density

- Cycles 1 to 3: -2 V
- Cycles 4 to 6: -4 V
- Cycles 7 to 9: -6 V
- Cycles 10...: -8 V




- Increase in current density
 - indicates corrosion at the metal coating interface and degraded coating
 - after 6 cycles for D sample compared to 22 cycles for S-sample


Results for D-primer



- IZI and Phase angle responds to the applied dc volts
- Failure could be induced by applying dc


Results for S-primer






- IZI and Phase angle responds to the applied dc volts
- Failure could be induced by applying do
- •S-sample however fails at higher cycle compared to D- sample


Influence of dc on barrier property






- |Z|_{0.01Hz} dissimilar for control and sample
- •Influence of dc on barrier property of both the samples

Analysis of S-primer data



- Cycles 16, 17 and 18: truncated data set at 0.1 Hz
- Lack of fit for sample data at cycles > 18

Analysis of D-primer data




- For D-control : R_{mci} and R_{coat} unchanged
- For D-sample: R_{coat} and R_{mci} similar for first 5 cycles

R_{mci1} and R_{mci2} required after 5 cycles


R_{coat}, R_{mci1} and R_{mci2} dropped off after 5 cycles

Post dc potential profile for D-sample



- Up to cycle 5, short time relaxation observed, characteristic of intact coating
- More than one time constant post cycle 5 indicating loss of coating intactness

Post dc potential profile for S-sample



- Relaxation behavior changes from cycle 21 indicating barrier property degradation.
- More than one time constant observed. Cycle 25 displays the OCP of the substrate when the coating fails completely

Application of AC-DC-AC on primers

- Based on barrier property $|Z|_{0.01Hz}$ and current density plots
 - 3 cycles of -4 V dc degraded D-sample
 - S-sample degraded after 11 cycles of –8 V dc
- Equivalent circuit analysis of EIS data
 - S-sample circuit included only R_{bulk} and R_{mci} until failure
 - D-sample circuit used R_{bulk} and R_{mci} when intact and R_{bulk} , R_{mci1} and R_{mci2} upon failing
 - Potential profile post dc also provides signature of coatings ability
 - Different relaxation behavior was observed that could discriminate between an intact and degraded coating
 - Future effort--- correlate ac-dc-ac findings with B117 exposure data for primers